



No.1: Cámara de alta temperatura

(65c—150c)

No.2: Cámara de alta temperatura y

humedad (0c—150c, 65%~98%)

No.3: Cámara de baja temperatura y

humedad (-40c—100c, 20%~98%)



México: [-52] 55-5300-4517, 55-53004271, 55-5312-2536  
Querétaro: [-52] 442-340-0250, 442-340-0251, 442-193-5678  
Puebla: [-52] 222-219-9999, 222-887-0114, 222-228-1633

[www.cmsmetrology.com.mx](http://www.cmsmetrology.com.mx)

[www.controlymedicion.com.mx](http://www.controlymedicion.com.mx)